

These articles and information is brought to you by The 1937 and 1938 Buicks Club. For more information please contact us at:

http://autos.groups.yahoo.com/group/1937and1938Buicks/ or WWW.1937and1938Buicks.com

#### -- Warning Notice --

It the mission and goal of 1937 and 1938 Buicks Club is to provide information, helpful hints, advice, directions and reference information for the repair, maintenance, authentic restoration and knowledge development in regards to 1937 and 1938 Buick's. Content is offered as informational only.


The 1937 and 1938 Buicks Club does not knowingly accept false or misleading content or advertising. Nor does The 1937 and 1938 Buicks Club assume any responsibility for the consequences that may occur should any such material appear.

The 1937 and 1938 Buicks Club does not guarantee the quality of any information which is included in this or any other publication. Under no circumstances shall The 1937 and 1938 Buicks Club be liable for any damages, losses, or injuries resulting from use reliance on the content of this or any other publication. Any reliance on this or any other publication content is at your own risk.

As a precautionary measure, The 1937 and 1938 Buicks Club strongly recommends that you contact a professional mechanic or restoration shop to check your work or answer specific questions.

#### -- Copyright Notice --

All rights reserved. All documents and publications on The 1937 and 1938 Buicks Club web site or that can be down loaded from The 1937 and 1938 Buicks Club web site are protected under both U.S. Federal copyright law and international treaties. No component of this site, including text, images and computer code, may not be reproduced or copied in any form or by any means--electronic, graphic, digital or mechanical, including photocopying or information storage & retrieval systems--without the express prior written permission of The 1937 and 1938 Buicks Club.



VOLUME XXI - NUMBER 4 - MARCH/APRIL 2003



Dear Members: We have a new Editor! The Club will continue! Mark Jordan (#1297) has agreed to take over in September as the new Editor. Mark has a 1938 Special Sedan and lives in Oakland, CA close to our Art Director Dug Waggoner (#10). Together they will continue to publish the Torque Tube. In case you want to contact Mark, his e-mail address is: torquetube3738@yahoo.com

There will be a new **Roster** included with your July/August Torque Tube. I would like all those who want their <u>e-mail address</u> listed in the new Roster to e-mail it to me as soon as possible. Send it to: harrylogan@earthlink.net. Thank you.

Our new member Stan South (#1707) in Escondido, CA recently purchased this black 1938 Buick Special Sedan Model 41. Stan says the body is in good shape but the trunk floor is rusted. The interior is original but need restoring. Note: We have 146 members who own this model, the most popular in the club.

Bob Hamro (#775) took this photo of a '37 Buick in a wrecking year about 10 years ago. Bob thinks it was a sedan. He says the yard was full of cars from the '30's and 40's and run by an older man. The yard probably no longer exists.









TORQUE TUBE



This next photo was taken at Fort Clark Army Base in Texas in 1938. Don't know who the three young ladies are, possibly soldier's wives. The car is a '38 Special coupe as indicated by the ivory colored steering wheel. A '38 Century coupe would have a mahogany (dark) colored steering wheel. Thanks to Charles Jekofsky (#524) for sharing this.

Many of us receive Sporty's catalog for home owners in the mail. Their January through April 2003 catalog shows a man using a car polisher on a '38 Century coupe. This car belongs to **Lou Wildt** (#245) in Ohio. The car still has it's original black paint. Thanks to **Bill Olson** (#427) for sharing this with us.



Here's something you don't see very often.
 Two 1938 Century Sport Coupes together.



The TORQUE TUBE is published every two months

Membership dues are \$34.00 per year U5, \$35.00 per

year Canada or Mexico and \$40.00 per year for all others. All issues mailed First Class and Overseas issues are mailed Air Mail-Printed Matter unless Surface Mail, at \$35.00 per year, is requested.

All memberships run September 1 to August 31 of the following year. Persons joining during the year will receive all back issues from September 1. All payments must be in U.S. funds. Please make your check payable to the 1937-1938 Buick Club.

Check ou the new 1937-1938 Buick Club web site: http://clibs.hemmings.com/1937-1938buick/

Please send all articles, ads subscriptions and inquires, etc. to:

The TORQUE TUBE 1005 RILMA LANE LOS ALTOS, CA 94022 USA You can reach Harry Logan by PHONE/FAX (650) 941-4587 or by E-mail: harrylogan@earthlink.net

Editor: Harry Logan, #651 Printer Liaison: Bill Olson, #427
Art Director: Dug Waggoner, #10 Printer: Conrads Printing, Lancaster, Ohio

All rights reserved. No part of this newsletter may be reproduced in any form without written permission from THE TORQUE TUBE



The one in the front is my dark gray with red wheels 38-66S and the one behind it is Tom Martindale's (#1198) beige 38-66S.


Here's another shot of the two Century Sport Coupes. Sport Coupes have two fold-down jump seats behind the front seat.

This is new member Bill Brook's (#1661) maroon '38 Century Convertible Sedan Model 60C. Bill recently purchased the car from Jerry Beall (#606) in Portland,

Oregon. Bill enjoys driving the car and is fixing some of its problems due to many years of storage. in February on eBay. Both are in pretty sad shape.



Here are two 1938 Specials that were for sale



The sedan still has its original faded Botticelli Blue (#516) paint. The coupe is now a rusty brown color. Don't know if they sold or not, Thanks to **Charles Jekofsky** (#524) for sharing these photos.


Garden of Speedin' (formerly Vintage Parts 411) has done its first huge update of its Buick Parts Locating Guide since it was first printed in 1996. The updated 2002 Edition is a highly organized book that makes it easy to find the best parts dealers in the country. "The new books are twice as good as the last editions," says president Adam Gimbel.

"There are hundreds of new sources and twice as much information on each page." While minor updates have been done every year or two, this is the first time the book has been revised top to bottom with new companies and categories. The book covers parts for ANY Buick for ALL years that Buicks have been made. The book contains chapters for part categories (body, interior, engine, etc.), literature, part restoration services, salvage yards, high performance parts, clubs and accessories.

The company has produced 14 editions for GM, Ford and Mopar cars and trucks. Each book comes with a 100% satisfaction guarantee. If you can't find your part, they'll refund your money. The price for each book is \$24.95 plus \$5.00 shipping and handling (tax is required for California residents). Call










1-800-MOTORHEAD (668-6743) for more information or write: The **Garden** of **Speedin' Inc.**, 4645Q Ruffner St., San Diego, CA 92111 or visit http:// www.gardenofspeedin.com.

This nicely restored beige '37 Special Business Coupe Model 46 was for sale on eBay in February. It was called a Sport Coupe in the ad, but had no jump seats. So it was really a Business Coupe.

It has a '36 steering wheel, heater and defroster but no radio. Note the radio blanking plate. There is a defroster deflector on the dashboard for the driver but not the passenger. Thanks to **Charles Jekofsky** (#524) for sharing this.

This 1937 Buick 80C Brewster Limousine was recently purchased by new member Ross Parsons (#1713) Phoenix in Arizona. This car is believed to be the only one built and is so described and pictured on page 170 of George Dammann's book "Seventy Years of Buick." Ross purchased the car from the estate of the late Russ Jackson (cofounder of the Barrett-Jackson Auction). Ross is trying to trace its ownership history. If any members has more in-









formation on the car, please e-mail him at: rossparsons@hotmail.com

This '37 Century Sedan Model 61 belongs to Anthony Wright (#1192) in New York City. The photo (bottom, page 5) was taken at Anthony's second home in upstate NY near the Catskills that he bought in 2000. In the background is a little farmhouse that was built in 1930. Anthony says he feels very comfortable in it even though he sometimes bumps his head. Out of sight is a larger barn where he keeps his old cars.

Here's Walter Fowler (#1195) and his '38 Century Sedan. Walter lived in Greene, New York. I was sorry to learn he died in February. His son Bill, who is in the US Army in Virginia, inherited his Buick and his Torque Tube subscription. Welcome to the club Bill.

1938 and 1937 Buicks of the Texas Department of Public Safety. Texas





Ranger Colonel Homer Garrison is in the dark suit. This photo was from a book on "Police Departments and Their Cars." Thanks to Richard Vaillancourt (#1171) for sharing it.

I welcome any input from members so please e-mail me with any questions you may have about the Torque Tube or your subscription. My e-mail address is: harrylogan@earthlink.net. That way you will get an immediate response (unless I am on vacation). I mention this because I have been receiving telephone messages on my answering machine from the East Coast and Europe, requesting a return call.

Notice the '37 convertible behind the hot rod. This photo was probably taken in






Southern California in the 1940's. Thanks to Charles Jekofsky (#524) for sharing it.

Received this photo of a 1938 Buick Special Sedan in Estonia from **Paul DeLucchi** (#1246) in San Francisco. No other information on the car.

This 1938 Special coupe below was for sale on eBay in March. It had 1940 sidemount covers and was in rough shape. Don't know if it sold or not. Thanks to *Charles Jekofsky* (#524) for sharing this.

This next story appeared on an Internet mailing list for Mercedes owners, which gets off the topic every one in awhile. There was recently a discussion about 1930's vintage Buick engines. Here is one of the stories.

"Hank wrote about his experiences with that great old engine, the Buick 320-ci straight-eight, and I can confirm how good an engine it was/is. Three times I drove across the US in a '36 Buick Century (which got its name from its top speed)



behind one of these 800-lb monsters. All they do is make torque and heat! Through the desert it was 117 degrees inside the car, so the next year we insulated the firewall."

"The three-speed transmission had one more gear than necessary; massive torque allowed you to start in second. The engine in this particular car had been converted to insert bearings; it was totally reliable and never missed a beat in 9,000 miles, including some runs at 80 to 100 mph."

"1936 was the year that Buick converted to juice brakes and independent front suspension, so the car even handled decently. As a result of the experience with this car, I had the serious hots for a pre-war Buick for some time!"

Here's another Internet photo below showing a cream '38 coupe at a Mobiloil gas station. Can any member name the other car next to the '38?

This 1938 McLaughlin Shop Manual was auctioned on eBay in January. The minimum bid was \$25. Don't know if it sold or not.







#### ANNOUNCMENT: WESTERN 37/38 TOUR

Salem, Oregon August 9-10-11-12-13, 2003

We'll meet in Salem on Saturday August 9. On Sunday August 10 we'll go to the All Buick Meet at Western Antique Powerland, home of Pacific Northwest Truck Museum and the Oregon Electric Railroad Trolly museum We'll tour the Oregon Gardens and the only Frank Lloyd Wright designed home in Oregon. This home was of the "Usonian" design and was featured in Life magazine in 1938. We'll drive to beautiful Silercreek Falls State Park and have a 1930's style picnic lunch. Then we'll go to Evergreen Aviation Museum in McMinnville to see the famous all wood "Spruce Goose" built by eccentric Howard Hughes and many other planes including an SR-71 Blackbird, the fastest jet

Howard Hughes and many other planes including an SR-71 Blackbird, the fastest jet ever built. At top speed, the Blackbird covered 35 miles per minute and carried cameras capable of photographing a golf ball on a green from 15 miles up.

Host hotel will be the

Phoenix Inn Suites 4370 Commercial St.S.E. Salem, Oregon 97302 Telephone: (503) 588-9220

Harry

#### NOTE TO MEMBERS


**Buick Restoration Services** advises that after being sold out of some 1938 and 1940 running board moldings, they will be fully re-stocked by mid-May.



Front Cover: This French bodied 1938 Special convertible Coupe belongs to John Steckbeck (#1621) in Fort Wayne, Indiana. John purchased it at an auction. This unique green 38-46C has a custom body by Letourneur & Marchand of Paris, France. See page 8 of the Jan/Feb 2001 TT for more information on this car. Rear Cover. Jamie Ratzken's (#1641) 1937 Century Sedan parked next to a patriotically decorated home in Sherman, Connecticut. That's the home owners in front. Jaime thought the car would add to home's decoration and it does.

## I LIKE OPEN CARS

By the Editor for Jack Shepherd (#138)-Canada




Longtime member Jack Shepherd (#138) in B.C., Canada has owned open Buicks for over 50 years. One of his favorites is this beige 1937 Century Convertible Sedan Model 60C that he restored after purchasing it from Greg Field (#1500) years ago. Jack brought it to the Western 37/38 Meet in Kent, Washington several years ago.

He recently sold his '38 Special Convertible Coupe Model 46C. But he still owns this 1931 McLaughlin Buick Model 64 Roadster he bought in the mid-1960's. It has never been restored.

The extra large wind wings were custom installed by the original owner to protect his children who often rode in the rumble seat.

Jack is suffering from Parkinson's disease and is now in a care facility. His address in case you might want to write him is:



Jack Shepherd Dover House 6155 Hammond Bay Rd. Nanaimo, B.C. Canada V9T 5M4

# Custom Bodied 1938 Buick Limited

By the Editor

his custom bodied limo showed up at Greg Field's (BCA#1) Los Angeles home in the early 1970's looking for parts. It is a 1938 Buick Limited with a custom body by Fleetwood and was painted black. It has suicide doors on both front and back. Wayne Yonce (#1034) remembers it being for sale in the Los

Angeles area in the mid-1970's for the grand sum of \$3,000.



was eventually owned by Gene Dick in Southern California. Gene Classic Wheels, a company that rented antique cars to movie studios. He had around 600 old cars. There were five other old car rental companies then but now they're all gone. Now studios rent

their cars from individuals or clubs. The studios keep a computer record of old cars they can Then someone added Trippe lights. The car rent and contact the owners or club directly.






Gene says one studio wanted the car's color changed from black to silver.

That's when he discovered that the car was originally a town-car with an open roof above the driver. Someone installed a wooden leatherette covered roof over the front seat and changed the car's original town-car look.



The Limited was in several films including "Poor Little Rich Girl: The Barbara Hutton Story" that was made in 1987 and "Harlem Nights" with Eddie Murphy, produced in 1989.

The car was owned by Chuck Roney in Azusa, CA. He bought it in 1985. He says the car has a roll-up divider window between the driver and



passengers and a speaker tube so the passengers can talk with the driver when the division window is rolled up. The car runs but has been stored in a garage for a number of years, so the brakes probably will need some work. He was asking \$15,500 for it. The car was recently sold to a collector in Nevada. Hopefully he will restore it.

## A MIXED UP BUICK

By George Gerberick (#136) - West Covina, California

Some years ago, a man phoned me asking for advice about his Buick. He knew that I had a 1937 Century and thought I had all the answers to his questions. I have talked to him over the years and given him what advice I could. The car still needs much work to bring it up to standard.

I finally decided that I should write and tell about his unusual Buick.



The Series 40 four-door sedan has had many unknown owner, many of whom made modifications so it's hard to tell what it is. It has a 1951 engine and the wheels from a 1936.



The steering wheel appears to be from a 1940. The dashboard is from a 1938. The firewall data plate indicates it is a 1937 as does the rest of the body. The car has leaf springs in the rear. The cut-out in the frame for the gas down tube is on the passenger side. Underneath the car appears to be all 1937 but on top it is all 1938. What is the answer?



Did someone go to all the trouble to change all of the 1937 sheet metal and trim to 1938? Did someone put a 1937 frame under a 1938 body? Was this a factory prototype for the 1938 car built on a 1937 frame? We will never know the answer to where this car came from and how it came to be. It's an interesting puzzle!

## FISHER & HOLDEN Souicks

By the Editor


Holden of Australia's car body history goes back to 1914 when they took an order for a custom built body for a Lancia chassis. One custom body led to another and over the next few years they built not only car bodies but also motorcycle side cars and even Ford Model T bodies. In 1923, General Motors Australia (GMA) indicated their desire to use Holden's as their sole body supplier. Then in 1931, GMA purchased Holden outright. GMA would import Buicks from the US minus the body and install their own.



The Holden bodied Buicks differ in minor details from Fisher bodied Buicks. For example, internal door handles and window cranks (winders) are quite different, as is the upholstery and the bumper bars. Only Special and Century sedans were Holden bodied. 1938 Roadmaster and Limited's were imported with Fisher bodies, but in very small numbers.



The Fisher body had the defroster (demister) vents in the windshield (windscreen) moldings and the windshield wiper switch on the top of the dash.



The Holden does not have defroster vents in the windshield moldings and the wiper switch is under the dash. And of course the steering wheel is on the wrong side.



This is the rear view of a Fisher body.

The Holden rear windows are shaped slightly differently. And none of the window regulators and other body parts are interchangeable.



This 1938 Holden bodied Century belongs to Neil Hodgin's father-in-law in Australia.


He is getting older and would like to see it go to a good home.

If you're interested in the car, contact Neil at: hodgins@austarnet.com.au


## HISTORY OF THE RUNNING BOARD

Courtesy of the New England CCCA Quarterly

Running boards became obsolete in the late 1930's. Our Buicks are among the last cars to have them. This obsolete feature is one of the things I like about our cars along with bucket headlights, 18" steering wheel, fender parking lights and long hood. But how did running boards get started?



"They originated with early fire fighting equipment. Horse drawn fire engines had little room for additional firemen to ride on and these souls sometime ran alongside the apparatus. Someone developed another piece of equipment, a skeletonlike wagon on which could be carried ladders, essential for reaching upper story fires. These long wagons had unused space lengthwise between the wheels on each side. Some builders arranged hooks there to carry buckets. Then someone took pity on the poor running firemen and installed a lengthwise shelf in there, replacing the bucket hooks, and this provided a place for the firemen to sit or stand. These became know as running boards and when cars became long enough so that a step plate was not enough for convenience in entering, the extended connection between front and rear fenders became known as running boards."



"Follow that car -and next time YOU get one with a running board on it!"

## BUICK FENDER SKIRTS






Buick offered factory fender skirts (at extra cost) for the first time in 1940.

Buick called them fender wheelhouse covers. Some of the cars displayed at 1940 Buick auto shows had them installed to show the public.

Unlike the 1941 skirts which had stainless trim, the 1940 skirts were plain. A few of our members have installed them on their Buicks. The diagram below on how to install them appeared in the 1940 Buick Parts and Service Bulletins.



NOTE: - CARS HAVING REAR FENDER GRAVEL SHIELDS MUST HAVE RUBBER SEAL ON EDGE OF WHEELHOUSE COVERS TRIMMED OFF. CUT TO FIT AS SHOWN IN SKETCH. THIS WILL MAKE COVERS FIT SMOOTHLY OVER THE GRAVEL SHIELDS.

COVERS HAVING ADJUSTING DEVICE AS SHOWN AT-C-PROCEED AS NOTED.


40-478



## **HOW TO INSTALL** RIPPE LIGHT


Thanks to Charles Jekofsky (#524) in Oregon for sharing these original factory instructions.

#### How to Install a Pair of Trippe Safety Lights



#### Mounting

- 1. Clamp bracket assembly A over supporting arm of bumper.
- Attach toothed end of arm B to toothed bracket A.
- 3. Attach ball end of srm B to socket on base of light.
- 4. Adjust fittings so lights are well back out of danger from minor traffic bumps.



#### Wiring

- 1. Run cable from each light through radiator grille, along each side of radiator core, and through some convenient opening in dashboard.
- 2. Bring cable ends together at desired switch location and twist securely to short wire F on switch, solder if possible, and tape.
- 3. Connect wire T of switch to terminal on main vehicle switch block which holds tail light wire.
- 4. Connect wire P of switch to battery lead wire at main switch block (ahead of fuse and ammeter).
- 5. Clamp switch to lower edge of instrument panel. Surplus cable can be taped into a coil.
- 6. Check all electrical connections.

#### Aiming


- 1. Drive car on a level surface such as a hydraulic grease rack or brake testing machine. If car has two seats and usually carries more than two passengers, have one person in back seat.

  2. Aim right Trippe Light straight shead and with level bubble exactly centered between the etched lines.
- 3. Aim left Trippe Light so the beam angles slightly to right and inclined slightly downward so level bubble is just a trifle behind its centered position.



Final Check on Aiming


THIS IS MOST IMPORTANT. IT MAY BE OUTTE POSSIBLE THAT THE SURFACE ON WHICH YOUR CAR RESTED WHEN THE LIGHT WAS AIMED WAS NOT LEVEL.



- 1. Stop car on level stretch of concrete. Have your assistant put a white envelope against his trouser leg, top of which is the same height from the ground as the cross bar in the center of the light.

  2. Have assistant back away about 25 feet.
- 3. Top edge of right light beam should not rise higher than the top edge of the envelope held by your assistant, as shown.
- 4. Top edge of left light beam should not rise higher than the bottom edge of the envelope.

  5. Beam of right light should go straight down the road, while beam of left light should angle very slightly to the right.



#### Lamp Replacement


- 1. Remove screw from spirit level ornament and remove ornament.
- Straddle pins on lens ring with pliers; contract ring, and then remove ring and lens.
- 3. Insert bulb and hold lens with flutes vertical over the light, and note whether top of beam is straight across the top and sharply cut off.
- 4. Remove bulb, give it a half turn, and re-insert. Hold lens over light same way as before and note beam. Whichever bulb position gives sharpest and straightest cut-off of top of beam is the correct one to use.
- Hold lens centrally against reflector gasket, being sure that the flutes are vertical. Force lens ring in against lens and behind retaining clip which curves up from bottom of light.
- Force in the remainder of the lens ring by compressing it with palms of both hands. Be sure lens is centered.
- 7. Replace ornament and screw.

#### Use Trippe Precision Bulbs Only for Replacement

6-8 Volt lamps, list price. 12-16 Volt lamps, list price. \$0.75 postpaid \$0.85 postpaid

Purchase from your dealer or from TRIPPE SALES COMPANY. 600 West Jackson Boulevard, Chicago, Illinois.

#### Don't Forget Your Trippe Wrench - Keep It Handy





## BUICK CARBURETORS

By Jon Hargrove

The Carburetor Shop - 204 East 15th Street - Eldon, Missouri 65026

Web Site: www.thecarburetorshop.com

Buick used Marvel carburetors for years due to the close proximity of the Marvel plant. When Borg-Warner bought Marvel in the early 1930's, they changed the mission of the Marvel company from automotive to tractor (Marvel-Schebler). This created problems for Buick in the early 1930's and they added a second supplier (Stromberg) to not be dependent on one supplier. In 1937, Delco (GM company) developed the automatic choke which Buick was chosen to test. At the same time Stromberg developed the AA series carburetor. The AA carburetor proved promising, and was extensively redesigned for 1938 becoming the AAV (the V meant vacuum economizer). The auto choke didn't work. Stromberg tried to talk GM into the electric or hot air choke in 1938, but GM really wanted the Delco unit to work (it never did), and Buick continued with the Delco choke. In 1939, with the demise of Marvel as an automotive supplier, Buick turned to Carter as a second supplier. GM finally gave up on the Delco choke, and both Carter and Stromberg were asked to supply replacement carburetors for the 1937 and 1938 Buicks. Both complied, and these replacements were available in the Buick dealerships. A large percentage of 1937 and 1938 Buick carburetors were replaced in1939 (people wanted to drive the cars!). By1939 the AA series was one of the finest carburetors available (my opinion). The major changes necessary to place a 1939 (or newer) carburetor on a 1937 or 1938 is to add an arm to the throttle to change the direction of throttle travel, and provide a stimulus to operate the choke.

For owners of 1937 and 1938 Buicks that drive their cars, we recommend the use of the original Stromberg only if they live in an area where the temperature does not fall below 70 degrees F. We cannot recommend the use of the original Marvel for these years anywhere for a "driver". For owners that have trailered show-cars, we suggest the Stromberg if possible.

#### MORE BUICK CARBURETOR INFORMATION

Received this e-mail from Luciano Nota in Argentina: Dear Sirs:

The reason for writing to you is that we are carburetor and fuel pumps rebuilders. We own hundreds of NOS and rebuilt carburetors for 1936-1950 Buicks. as well as fuel pumps and obsolete Buick parts. The NOS products includes the original packaging. We can offer you Carter WCD, WD-O and Stromberg AA, AAV and AAUV. The fuel pumps are NOS AC combination (fuel and vacuum). The prices are very low. Just contact us if you have any question. We will answer as soon as possible.

Their e-mail address is: mondeov6@yahoo.com

#### CARBURETORS IN STOCK

1935-1940 Carter WD-O 419S

1936-1940 Carter WD-O 448S

1937 Stromberg AA-1 A-18361 A-18451

1937 Stromberg AA-1 A-18362 A-18452

1937-1938 Stromberg AAV-167 380861

1937-1938 Stromberg AAV-167 380242

1937-1938 Stromberg AAV-267 380243

1938 Stromberg AAV-1 A-18161 A-18691

1938 Stromberg AAV-2 A-18682 A-18692

1939 Stromberg AAV-16 A-18971

1939 Stromberg AAV-167 380244

1939 Stromberg AAV-26 A-18972 A-18982

1939-1940 Carter WD-O 440S

1940 Stromberg AAV-167 380238

1940 Stromberg AAV-26 A-19192

1940 Stromberg AAV-267 380240

1940 Stromberg AAV-267 380867

1940 Stromberg AAV-26 A-19182

1940 Carter WD-O 474S

1941 Stromberg AAV-16 380064 380066

1941 Stromberg AAV-16 380032

1941 Stromberg AA-1 380043 380067

1941 Stromberg AAV-16 380042

1941-1942 Stromberg AAV-16 380029 380103 /4

1941-1942 Stromberg AAV-167 380236

1941-1942 Stromberg AAV-167 380239

1941-1942 Stromberg AA-1 380095 380096

1941-1947 Stromberg AAV-267 380241

1942-1947 Stromberg AAV-26 380097

1942-1950 Stromberg AAV-16 380103

1946-1947 Carter WCD 6085, SA, SC

1946-1947 Carter WCD 6095, SA

1948-1949 Carter WCD 608SC 663S

1948-1949 Carter WCD 609SC 664S

1948-1949 Stromberg AAV-267 380226

1948-1949 Stromberg AAV-207 380225

1950-1951 Stromberg AAUVB-267 380257

1950-1951 Stromberg AAVB-267 380310

1950-1951 Stromberg AAVB-267 380258

YEAR	MODEL - SERIES	# OF CYL.	CARB # or type	JET# OF Manufactur	Part#	
1935	40	8	EDIS	Marvel		
1935	50	8	EEI	Marvel		
1935	60	В	ED2S	Marvel		
1935	90	8	ED3	Marvel		
1936	40	8	BD1	Marvel	1	
	7.5		BD1	Marvel		
1937	40	8		Marvel	1	
1938	40 60,80,90	8	CD1	Marvel		
1938	60, 80, 70	D	CDE	Marvel	the same of the same of	
1935	40	8	Stromberg		A17671(4)	A17681(5)
1936	40	8	Stromberg		A18181	A18191
1936	60, 80, 90	8	Stromberg		A18302	A10312
1937	40	8	Stromberg		A18361	A18541
1937	60, 80, 90	8	Stromberg		A18362	A18452
1938	40	8	Stromberg		A18861	A18452
1938	60, 80, 90	8	Stromberg	SVAA	A18682	A18692
1939	40	8	Carter	4195	WDO	
1939	60, 80, 90	8	Stromberg	AAV26	A18972	Late 4405 w
1940	40 &50	8	Stromberg		A19181	
1940	60, 70, 80, 90	8	Stromberg		A19182	
1940	60, 70, 80, 90	8	Carter	448S	WDO	
1940	60, 70, 80, 90	8	Stromberg	AAV36	HDAC	19192
	50 Rear	8	Stromberg		15/16	380043
1941-42	50 Front	8	Stromberg		380042	2000.00
1941-42	50 Front	8	Carter	509 or	528	
1941		8	Carter	510 or	529 or 543	
1941 42	50 Rear				367 01 343	
1941-42 Single	40,50 Single	8	Stromberg	AAVIO	608,663	
1941-42 Single	40, 50 Single	-	Carter			
1941-42	60, 70, 90 Single	8	Carter	549,664	525	
1941-42	60, 70, 90 Front	8	Carter		,543,544	
1941-42	60, 70, 90 Rear	8	Carter			
1941-42	60, 70, 90 Front	8	Stromberg		380032	
1941-42	60,70,90 Rear	8	Stromber		1 1/16	
1946-47	40&50	8	Stromberg		&AAV167	
1946-47	40&50	8	Carter	608,663		
1946-47	70	8	Stromberg			
1946-47	70	8	Carter	609,664		
1942-47	60, 70, 90	8	Stromberg		AAV267	
1942-47	60,70,90	8	Carter	609,664		
1948-49	40,50	8	Stromberg	AAV167	1 1	
1948-49	40,50	8	Carter	663 608		
1948-49	70	8	Stromberg			
1948-49	70	8	Carter	664 609		
1950-51	40-50	8	Stromberg			
1950-51	40-50	8	Carter	725,882		4 base
1950-51	70	8	Stromberg			
1950-51	70	В	Carter	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	883 with 626	base
1952-53	40	8	Stromberg	AAUVB		
1952-53	40	В	Carter	882 or	883 with 624	base
1952	70 4 bore	8	Stromber	4AUV26	7	
1952	70 4 bore	8	Carter	8949-SA		
1952	40 & 50 2bbl.	8	Stromberg			
1952	40&50 2bbl.	8	Carter	8965		
1953	40 Zbbl.	8	Stromberg	7.100.000.000.000	267	
1953	40 Zbbl,	8	Carter	8825		

Fernished by Al Weatherly BCA 47786 Buick Unlimited

ED: Stromberg made two models of the AAV-2 Carburetor for 1938. One for Buick and one for Chrysler. They are NOT the same. If you are buying a Stromberg AAV-2 for a 1938 Buick, make sure the base is marked like this: P-23359 AAV-2



By Pat Jacobs (#1308)-Washington

## REPLACING THE COWL VENTILATOR SEAL


The last time I got caught in a major rain storm in my '38 sedan, I found that my cowl ventilator leaked, especially while parked, with the front just slightly downhill. Inspecting the seal revealed that the "rubber" was hard, and badly deteriorated. Not surprising after 65 years!

I ordered a new one, and then studied the body manual for information as to how to take the ventilator apart, as it was apparent that would be required. Unfortunately, like most manuals, the instructions were not clear, nor pictures adequate. I read and re-read the manual, after getting my head up under the dash. My ventilator has only four "adjustment" bolts, the manual says six. Second, it was not clear, if they should be removed, or the four hinge bolts, two at either end.

I disconnected the lever, then removed the

hinge bolts. The ventilator would not come out; not enough clearance for the hinge extensions. So, I had to remove the "adjustment" bolts. Why didn't it say so in the first place? Then I removed the old seal, scraped the groove clean, and installed the new seal. Of course, it was made a tiny bit too small, so had to stretch it to get it to fit, and then had to hold it in place for a while until the weather-strip adhesive would hold it in place while replacing the ventilator.


To my happy surprise, the bolts went back in with ease, and I did not have to have help, as the manual suggested to get it aligned properly. Putting it back was easier than getting it out, except for having your head between the transmission hump and the heater, and your feet up over the back of the front seat!



### BUICK SERIES 40 & 60, 80, 90 FLYWHEEL RING GEARS



By Gene McCoy (#573) New York



BUICK '34 TO '38 SERIES 40. BUICK PART NUMBER1267062 146 teeth, outside diameter is14.619 inches, width 9/16 inches.

- · Republic Gear Co. Number 146bf
- · Perfection Gear Co. Number 146cbf
- Double Diamond Gear Co. Number 618 ( old # 00146sxf)
- Super Gear Co. Number146sf,146bf,146cbf
- · Wohlert Gear Co. Number 146cbf
- · Accurate Gear Co. number is the same as Republic.
- Borg Warner Gear Co. number is the same as Super.
- · Permite Gear Co. number is the same as Double Diamond.

NOTE: These numbers are for the RING GEAR ONLY, NOT the flywheel and ring gears together.

BUICK '36 TO '38 SERIES 60, 80, 90. NUMBER 1286787 156 teeth, outside diameter 15.617 inches, width 13/16 inches.

- Republic Gear Co. Number156BSF
- Perfection Gear Co. Number156SFR
- Double Diamond Gear Co. Number 625
- Super Gear Co. Number 156CF, 156 BSF, S156SF
- · Wohlert Gear Co. Number \$156SF
- Accurate Gear Co. Number same as Republic
- · Permite Gear Co. Number same as Double Diamond
- Borg Warner Gear Co. Number same as Super Gear Co.

NOTE: These numbers are for the <u>RING GEAR ONLY</u>, NOT the flywheel and ring gears together.

If you need a Flywheel Ring Gear, take the list with you when you go to shows and swap meets.

Or keep it handy when you are talking to venders and parts suppliers.



By Gene McCoy (#573) New York

## 1937 & 1938 SERIES 40 TRANSMISSION GEARS


If you need transmission gears, take the list with you when you go to shows and swap meets.

It lists transmission gears made by Warner, Republic and

New Process Gear Companies for '37 & '38 Specials.

#### TRANSMISSION GEARS 1937 BUICK SERIES 40

	**WARNER	REPUBLIC	NPG
1 MAIN SHAFT	WT187-2H	K205-9H	236-8G
2 MAIN DRIVE	WT187-16H	K205-1C	TS236D
32 & 3 SLIDING SLV	WT187-2 1/2B	K205-23	236-1
4 COUNTERSHAFT	WT187-3	K179-10	214-9
5 CLUSTER	WT187-8A	K205-11	236-10
6 IDLER GEAR	WT187-10A	K205-8	236-7
7 2" SPEED GEAR	WT187-11A	K205-5	236-4
# LOW & REV	WT187-12A	JC205-3	236-2
9 IDLER GEAR SHAF	T WT187-35A	K179-12	236-11



(10 5/8" LONG) (9 1/16 " LONG)

#### TRANSMISSION GEARS 1938 BUICK SERIES 40

MAIN DRIVE	WT187-16K	K238-1	236-F
2 & 3 SLIDING SLV	WT187-2 14 C	K238-23	236-LB
COUNTERSHAFT	WT187-3A	K238-10	236-9
2 <sup>nd</sup> SPEED GEAR	WT187-11B	K238-5	236-4B

\*SMALL PARTS KIT SP187-50A OR 50B K205-40

THE '34 TO '38 OLDS 6 & 8 AND '36 TO '38 PONTIAC 6 & 8 USE MOST OF THESE GEARS

( NPG = NEW PROCESS GEAR COMPANY)

\*\* WARNER AND PERFECTION NUMBERS ARE THE SAME.

1 = '37 & '38 SERIES 40

7 = '34 - '35 SERIES 40,50, '36 - '37 SERIES 40

2 - '37 SERIES 40

8 = "34 - '35 SERIES 40,50, "36 - "38 SERIES 40

3 = '34-'35 SERIES 40,50, '36-'37 SERIES 40

9 '34 - '35 SERIES 40,50, '36 - '38 SERIES 40

4 = '34 - '35 SERIES 40,50, '36-'37 SERIES 40

5 = '34 -'35 SERIES 40,50, '36 -'38 SERIES 40

6 = '34 '35 SERIES 40,50, '36 - '38 SERIES 40

#### **ADS FOR CLUB MEMBERS ARE FREE!**

After your ad has appeared <u>once</u>, the Torque Tube will rerun it <u>one more time</u> if you ask. The best way is to e-mail or mail your ad. Include a photograph if you wish. See the masthead on page 2 for Torque Tube's e-mail and postal mailing addresses. If you want to run an ad continuously, inquire about our business ad rates.

## Parts FOR SALE

• 1938 PARTS FOR SALE: 1938 Buick straight eight Special engine. Co	mulate with early set or
starter and transmission. Not running	
Rear end with driveshaft	
Jimmie Wood (#1688)	
4145 Schindler	
Fallon, NV 89406	
Phone: (775)867-3762	
• 1938 PARTS FOR SALE:	
	ot damaged \$100
Robert Reed (#1183)	-
26 Norman Drive	
Birmingham, AL 35213	
Phone: (205) 871-2230	
E-mail: MBREED35@MSN.COM	
<ul> <li>1936-37-38-39 PARTS FOR SALE:</li> <li>REAR brake hose for Convertible. This is to extra thick mounting shoulder for proper convertible frame. Replaces Buick # 129-Totally correct, original look. Fits 1936, 1938-39, all convert.; and 1941-49, 51C, available.</li> </ul>	the odd rear one that has the r, tight installation in the heavier 4853 and superseding # 1294854. all convert.; 1937, 80C; 56C, 71C, 76C. Have several
<ul> <li>REAR brake hose for most of the same yea application. Replaces Buick part # 12882 convertibles; 1937, all except 80C; 1938 50, 60, 70, except convert. Have several</li> </ul>	256. Fits 1936, all except -39, all except convert.; 1941, 40, available \$16.00 each
<ul> <li>PAIR inner rear wheel seals for 1937-42, 8 part # 1296913.</li> </ul>	0 and 90 series. Replaces Buick
<ul> <li>PAIR outer rear wheel seals for 1937-42, 8</li> </ul>	0 and 90 series. Replaces Buick \$22.00 a pair
<ul> <li>PAIR front wheel grease seals for 1937, 19.</li> <li>1932 and 1933 Buick, 50 series. 1934 an</li> </ul>	38, 1939 Buick, 80 series; also
Buick, 60 and 80 series. Replaces Buick pa	rt # 1255825 \$15.00 a pair
Shipping is extra on all items.	
John Koutre (#593) 2331 Rainbow Drive	, Plover, WI 54467
Phone: (715) 341-6188 E-mail: drjjko	ot@g2a.net

(Parts For Sale Continued from page 25)	
• 1937 & 1938 PARTS FOR SALE:	
Water pump, rebuilt, 40 series. Core charge \$35	\$85
Water pump, rebuilt, 60-80-90 series, core charge \$35	\$85
Generator, Autolite Shunt, 6v-50 Amp, for ambulance etc	
Headgasket, 248 c.i., new	
Gasket Set-Valve grind, new, 248 c.i	
Rotor	
Point set	
Steering knuckle upper shaft pivot seal	
Steering knuckle support lower control arm kit, 40-60	\$25
Oil pump body gasket	
Tie rod end, Right, NOS, 37 all, 38-40 series	
Bushing, Steering knuckle support, NOS, 40-60	
Bushing, Shock absorber lower front, all series	
Nut, steering knuckle spindle, left, 40-60 series	
	33
Interior plastics available for 1937-38 and many other years	
For a price list, contact:	
Al Bell, Buick Parts	
4982 Hubner Circle	
Sarasota, FL 34241	
Phone: (941) 927-3588	
FAX: (9412) 926-8224	
E-mail: buickpts@comcast.net	
Specializing in Buick parts: 1914-1958	
• 1937 PARTS FOR SALE:	
40-60 Locking door handle, 1st type with offset shaft	
40 Second speed gear	
Throughout bearing	
40 Third gear front syncro drum	
40 Main drive gear or second speed gear. Specify	
40 steering gear pitman arm	\$30
• 1938 PARTS FOR SALE:	
Color sales catalog, black cover, good used	\$55
Carburetor vacuum starter switch	
40 Second and third gear synro drum	\$40
60, 80, 90 Main drive gear	\$55
40 Main drive gear	\$45
• 1937 & 1938 PARTS FOR SALE:	
40-60 Steering box pitman shaft bushings	\$15 pair
Headlight dimmer switch, NORS	. \$10 each
60, 80, 90 Transmission rear bearing	\$35
40, 60 upper outer, lower outer steering pivot pin kit. NORS	
1937 all, 1938 80, 90 left outer tie rod end, NORS	
All parts NOS except as noted. Add 15% postage.	
Have much more 37/38 mechanical, trim parts.	
Send SASE for list.	
Bob Graves (#1136)	
56 Dartmouth St.	
Lynn, Mass. 01904	
Phone: (781) 593-9534 evenings	
The state of the s	

(Parts For Sale continued from page 26)	
• 1937 ROADMASTER PARTS FOR SALE:	
Bare block, stock bore	\$45
Crank, standard size	\$30
Short block with crank, psitons, cam	\$85
Deck lid, rust at bottom edge	
Dual sidemount fenders, no covers, need body work	\$350 pair
Rear end with torque tube. No brakes or drums	
3.7 ratio rear end from 1936 Century, with torque tube	\$375
Transmission, shifts good	
Engine, rebuilt, removed from running car. No carb or manifolds	\$1600
• 1937 SPECIAL PARTS FOR SALE:	
New clutch, pressure plate	\$85
• 1937 ALL SERIES PARTS FOR SALE:	
4 Terminal Delco Remy regulator, rebuilt?. Was in box	\$40
Front nose body section. Holds grille. No dents or air baffle	\$70
Dave Powers	
27732 Paseo Barona	
San Juan Capistrano, CA 92675	
Phone: (949) 493-1199	
E-mail: davepowers@cox.net	


#### 1937-1938 CONVERTIBLE COUPE WINDOW FRAMES

Made in USA.

Double lapped construction and radius edges as original. Drilled for right or left. Ready for plating. Will make on order for the next 90 days only


then we are done.
So if you'll be needing one in the future, order now.
\$200.00 each plus shipping.
Lauren Matley (#46)
13912 SE 241st Street
Kent, WA 98042

e-mail lkmatley@hotmail.com



#### 1938 NOSE BADGE

Excellent reproduction.
Chrome plated brass like original.
Painted as original.....\$110
Price includes shipping in the USA.



Joe Krepps 2486 S. Pacer Lane Cocoa, FL 32926 Phone or FAX: (321) 636-8777 E-mail: buicknut@palmnet.net

## Liturature FOR SALE & WANTED

#### FOR SALE:

Old issue of Collectable Automobile magazine | featuring 1936 to 1992 Buick Roadmaster.

Excellent coverage. Mint condition \$12.00

Ronn Pittman (#1188) 1024 S. Raddant Rd. Batavia, IL 60510 Phone: (630) 879-7393

#### **OLD TORQUE TUBES WANTED:**

Need: •Sept/Oct 1993 •Jan/Feb 1994

•Sept/Oct 1994 •Nov/Dec 1994 •Jan/Feb 1995

•March/April 1995 •May/June 1995

•July/August 1995

Ronn Pittman (#1188)

1024 S. Raddant Rd., Batavia, IL 60510

Phone: (630) 879-7393

## Gars FOR SALE

#### 1937 CENTURY FOR SALE:

1937 Century Trunk Back Sedan Model 61

No rust. Always garaged. 75,000 original miles.

Won first place at several car shows.

Photo on back cover **\$22,000** negotiable

Jaime Ratzken (#1641) 21 Satterlee Road New Fairfield, CT 06812

Phone: (203) 746-3630



#### 1937 CENTURY FOR SALE:

1937 Century 37-61 4-Door Black Sedan. Rare Original 103 K miles, 15 year California owner, runs great. 320 straight 8, original nice interior, new W.W.W. tires & original spare, rebuilt starter & solenoid, rebuilt water pump & fuel (electric).

Rebuilt stromberg carburetor, new



battery-6 volt, new master cylinder, new wires, plugs, rotor, condenser, new hoses (lock roll clamps), nice harness, 4 new Hubcaps, No leaks, No burn, Manuals galore, California Black/Yellow/Plates, foggs + many extras, N.O.S. in trunk. Car Located in Northern California.

Steve Nathanson (#656)

Call: (925) 947-6711

E-mail: my37buick@aol.com

See on the Internet at: www.antiquecar.com

## New Members

Ross Parsons (#1713) 1820-1 E. Frier Dr. Phoenix, AZ 85020 37-80C

Anthony Silorsky (#1714) 7 Collyer Drive Ossing, NY 10562

Parker Key (#1715) 3509 Meadowdale Drive Baltimore, MD 21244 38-46S Alfred Buescher (#1716) 137 Marble Canyon Drive Folsom, CA 95630

Sidney Boland (#1717) 1711 North Main St. Salisbury, NC 28144

J. Nathan McWilliams (#1718) 1709 Old Lee Hwy Tuscumbia, AL 35674

#### 1937-1938 Buick "HOOD HINGES"

All Stainless Steel reproduction of the Original Trim Orders Cut To Length To Git Your Model and Year

> \$195 plus shipping and tax (CA)

Bobs Specialty Parts 9282 Sungold Way, Sacramento, CA 95826 (916) 362-2597

## Back Issues Still Available!

The following Back Issues of the Torque Tube are available for \$5.00 each postpaid

- 1997-1998 Volume XVI Numbers 1 through 6
- 1998-1999 Volume XVII Numbers 2 through 6
- 1999-2000 Volume XVIII Numbers 1 through 6
- 2000-2001 Volume XIX Numbers 1 through 6
- 2001-2002 Volume XX Numbers 1,3,4,5 & 6

Please make your checks payable to:

The 1937-1938 Buick Club, 1005 Rilma Lane, Los Altos, CA 94022 USA

## 1940 BUICK SUPERS BY VICTORY MODELS



\$ 139% each



VISA

CATALOG #35

\$2.00

VL-3 1940 BUICK SERIES 50 SUPER 4 DR SEDAN

VL-10 1940 BUICK SERIES 50 SUPER CONVERTIBLE COUPE

### 1938 BUICK SPECIALS



VL-1 1938 BUICK SPECIAL SEDAM ALSO: VL-2 1938 BUICK SPECIAL BUSINESS COUPE Vac

SCALE

IN MET. BROWN or MET. GRAY

VL-4 1938 BUICK SPECIAL CONVERTIBLE COUPE OPEN ALSO: VL-5 1938 BUICK SPECIAL CONVERTIBLE COUPE W/TOP

SHIPPING \$6.00 first model, & \$1.00 ea ch additional mo del — Send Inquiries and Checks Payable to:

#### RAY PASZKIEWICZ, JR.

P.O. BOX 156, CLARKSBURG, N.J. 08510 . TEL. 732-446-9381 . FAX 732-446-9297

#### 1904-1965 BUICK RESEARCH SERVICE

More information and detail about your specific 1937 or 1938 Buick year, model and serial number than you can get from any other source. SATISFACTION GUARANTEED.

Complete Research Package \$50.00, \$60.00 if shipped outside the USA.

Additional information available at http://www.OldBuickArchive.com. Also check out 1937 and 1938 in the "Valve-In-Head Archive" at the web site for a listing of reference material that can be photo copied for research purposes.

#### 1937 BUICK HIGH QUALITY VIDEO

1937 Buick video made from the only known copy of a 16 mm black & white sound film produced by Buick Motor Division in 1937. The tapes have been made by a professional video dubbing studio. They are very high quality and are produced from a digitally mastered original. Video runs approximately 32 minutes and contains a number of segments showing the construction of the 1937 Buick and Buick's place in American society. Historically significant item. SATISFACTION GUARANTEED. \$39.95 including shipping.



## TERRY DUNHAM AUTOMOTIVE RESEARCH SERVICES

Buich

P.O. Box 4057, Apopka, Florida 32704-4057 e-mail: Buickohy@aol.com • web site: www. OldBuickArchive.com

#### 1937-38 BUICK






DOORWEAT	THERSEAL-SPONGE		
Glue-in	DW-378	\$1.90	n.
Clip-in	DW-80	\$3,50	ft.
Clips	WC-80	\$0.75	eu.











TRUNK SEAL-SEDANS 1/2" Wide; Ser. 80-90......TW-371...... \$44.50 Sedans, 3/4" Wide: Ser. 40-60......TW-371S....... \$44.50

HOOD REST PADS. 1937-38 6-8 Per. Car.




TRUNK SEAL For COUPES, 5/8" x 1" 1/2"x1"x16'.....TL-1129..... ... \$48.50



1937-38 Floormats Brown or Black \$225.00 ca.







PEDAL FLOOR SEALS; All Models

CLUTCH and BRAKE PEDALS Ser. 40-60



OUTSIDE DOOR HANDLE CHROME and RUBBER GROMMETS. 1 FERRULE & 1 GROMMET Per Set. 1937...... DF-296...... \$9,50/Set

... DF-380...



1937 ONLY! ACCELERATOR PEDAL Ser 40-60 Black......AP-37B...... \$34.25 Brown.......AP-37BN.................\$39.00

FS-375...... \$12.95 pr.





SHIFT BOOT, 1937-38 Series 40 Only! Black \$9.75 



1938 TRUNK HANDLE/LIGHT MOUNTING SEAL DH-381 59.75



DOOR SILLS; Trim To Fit 2-Door.... .... 572.00 pr.

CARR KITS: CARTER

VISOR "VANITY" MIRROR.



MOTOR MOUNT, FRONT. All Models

ROUND PADS......SP-338....... \$12.50 pr. ....MM-347..... \$52.50 pr.



GLOVE BOXES..... PARKING LIGHT LENS..... \$19.95 ca



1937 HUB CAPS. All Ser......HC-37..... Wheel Beauty Rings 15"or 16"..... ...\$115/ Set of 4



CK-360C... 

1937 HOOD ORNAMENT......



TORQUE BALL SEAL KIT. All Models



SOME OTHER ITEMS WE STOCK; BEARINGS, Decals, Engine Paint, Shop Manuals, Parts Books, Body Books,

LICENSE PLATE FRAMES. Chromed Brass LF-333P \_\_\_\_\_ \$62.00 Pair



SHIPPING (Unless otherwise noted on

1	FRONT END PARTS For 40-60 Ser	ies;
	Upper Outer Kit	\$39.50
	King Pin Sets	\$42.50
	Lower Inner Bushings	\$22.50
	Tie Rod End.	527.00



Minimum Shipping Charge...... \$5.95 \$17.50-\$49.00 Order..... \$50.00-\$99.99 Order..... \$100 and up.....

0000000

BOB'S AUTOMOBILIA BOX 2119 ATASCADERO, CA 93423 TELEPHONE (805) 434 - 2963 VISA - MASTERCARD - DISCOVER OR C.O.D. CATALOG #49 \$5.00 OR ONLINE AT bobsautomobilia.com

PRICES SUBJECT TO CHANGE WITHOUT NOTICE

TT-Jan/Feb-03

### BUICK...Upholstery and Top Kits 1927/1955

Since 1977.. Hampton Coach has been producing only the finest quality Interior and Top products available for GM cars.

We offer complete interior Kits Seat Upholstery, Tops and related accessories as well as "era" fabric by the yard... Inquire Toll Free... for Free Literature, Prices, Fabric Samples and Parts Catalog...

1-888-388-8726



HAMPTON

6 Chestnut Street (Cach) Amesbury, MA 01: Tel 978-388-8047 Fax 978-388-11



#### 1937-38 BUICK PARTS

- A VARIETY OF

### NOS, USED & REPRODUCTION PARTS

Gauges, Handles, Mirrors Interior Detail Items & Plastics, Belt Molding, Fuel Sending Units, Some Mechanicals PLUS MUCH MORE!

FOR A FREE LIST, CONTACT:

#### AL BELL BUICK PARTS

4982 Hubner Circle Sarasota, Fl. 34241 Phone: 941-927-3588 Fax: 941-926-8224 Email: buickpts@aol.com

SPECIALIZING IN BUICK PARTS 1915-1969



## J.B. Donaldson

2533 W. Cypress St. Phoenix, Arizona 85009 (602) 278-4505

Beautifully Recast

STEERING WHEELS

Call or write for brochure



RESTORATION



SERVICES

Running Board / Rocker Moldings

1934 thru 1940

SSAE for Information

BUICK RESTORATION SERVICES

P.O. BOX 442, PERRY,

MICHIGAN

48872



## 1927 thru 1953 Wiring Harnesses

AUTHENTIC REPRODUCTION
WIRING SYSTEMS THRU 1953
• HAND CRAFTED WITH THE
FINEST MATERIALS

• LIMITED WARRANTY

• INSTALLATION INSTRUCTIONS

SCHEMATICS

ALSO OFFERING:

WIRING SUPPLIES
 CATALOG OR INFORMATION \$5

HARNESSES UNLIMITED

BOX 435 WAYNE, PA. 19087

